

Huijue headlight high low beam module malfunction

Overview

Code B2580 indicates the Body Control Module (BCM) detected a short or open circuit in your high beam headlight system. The most frequent causes are a chafed wiring harness, a blown fuse, a faulty relay, or improperly installed aftermarket LED bulbs. If your low-beam headlights aren't working, this article will help you examine and fix the common issues that cause the problem. On 2015-2020 GM trucks and SUVs, this code is. When your low beams refuse to illuminate while the high beams blast on like nothing's wrong, it's confusing and unsafe. Faulty Bulb: The headlight bulb itself may have burnt out or become damaged. more Audio tracks for some languages were automatically generated. Understanding the possible causes behind this issue is crucial for resolving it promptly.



Article Content

Oct 07, 2025

High Beam Headlights Not Working (Here Is How To Fix!)

This troubleshooting guide has explored common reasons behind high beam headlight malfunctions, including bulb issues, wiring problems, fuse and relay issues, and headlight switch malfunctions.

Jan 04, 2026

OBD-II Code B2580: Headlamp High Beam Control Circuit Malfunction

Code B2580 indicates the Body Control Module (BCM) detected a short or open circuit in your high beam headlight system. The most frequent causes are a chafed wiring harness, a blown ...

Nov 22, 2025

How to Fix a Low Beam Headlight: 13 Steps (with Pictures)

Fortunately, fixing a bad low beam is a straight forward process in the majority of vehicles that can be done by most people without just a few hand tools. If replacing your headlight bulb does ...

Jan 02, 2026

Low beam headlights not working: How to fix — Ricks Free Auto ...

When they malfunction, it can be both a safety hazard and an inconvenience. If your low-beam headlights aren't working, this article will help you examine and fix the common issues that ...

Jan 20, 2026

How To Fix Car Headlights Not Working On High Beam (Simple

In this video tutorial I will show you how to fix car headlights not working on high beam. When driving under a rainstorm or at night, you depend on headlights to lead the way.

Jul 18, 2026

One or Both Headlights Not Working? Learn the Causes & Fixes (2026)

Is one or both of your headlights not working? Learn about the reasons behind low beam and high beam headlight issues and how to solve them with our in-depth guide.

Oct 22, 2025

Low Beam Headlight Nightmare? We've Got The Remedy That'll Light ...

In this comprehensive guide, we will delve into the causes and solutions for a low beam headlight not working, empowering you to restore your vehicle's illumination.

Nov 13, 2025

Why Headlights Beam Stopped Working And How To Fix It?

Thus if you notice either the high beam or low beam headlights aren't working, the cause may be a defective bulb. If the headlights are still not working after replacing the bulb or if more than ...

Dec 07, 2025

4 Symptoms of a Bad Headlight Relay (and ...

When headlights mysteriously stop working, a faulty relay is often the culprit. This small but critical component controls power flow to the headlight ...

Aug 11, 2025

Car's Headlights Won't Turn On But High Beams Work — Diagnostic ...

Most cases where high beams work but low beams don't are solved by starting simple: check the fuse, swap the relay, and inspect the headlight switch. Only after those steps fail should ...

Jan 29, 2026

High Beam Low Beam headlight Wiring Diagram

Don't be surprised if one day your car's headlights start malfunctioning and eventually die out. You should always be prepared to replace them when such an instance happens. That's why we ...

Aug 17, 2025

Headlight Control Module Failure Signs & Diagnosis

Most headlight failures stem from burned-out bulbs or corroded sockets, but when both headlights malfunction together, dim without reason, or respond erratically to the light switch, the control module ...

Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: <https://www.iiss.co.za>

Email: sales@iiss.co.za

Phone: +27 63 174 2895

Address: Unit 8, Innovation Park, 15 Rivonia Road, Sandton, Johannesburg,
2196, South Africa

This document is for informational purposes only. Specifications subject to
change without notice.

